



PATENT
DOCKET NO. 2390/49902

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

APPLICANTS: Jacob RICHTER et al.
SERIAL NO. : 10/066,755
FILED : February 6, 2002
FOR : METHOD OF MARKING A BIFURCATED STENT WITH
IMPROVED SIDE BRANCH APERTURE

ASSISTANT COMMISSIONER FOR
PATENTS AND TRADEMARKS
Washington, D.C. 20231
ATTN: Manager, Application Division

REPLY TO NOTICE TO FILE MISSING PARTS


SIR:

Enclosed herewith are the following:

- (1) Copy of Notice to File Missing Parts of Application, dated March 5, 2002; and
- (2) substitute drawings in compliance with 37 CFR 1.84.


The Commissioner is hereby authorized to charge the fee of \$130.00, required by 37 C.F.R. § 1.16(e), to Deposit Account No. 11-0600. The Commissioner is further authorized to charge any additional fees or credit any overpayments associated with this reply to Deposit Account No. 11-0600. A copy is enclosed for accounting purposes.

Respectfully submitted,


John C. Altmiller
Registration No. 25,951

Dated: May 6, 2002

KENYON & KENYON
1500 K Street, N.W., Suite 700
Washington, D.C. 20005-1256
(202) 220-4200 (T)
406444v1



UNITED STATES PATENT AND TRADEMARK OFFICE

COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK OFFICE
WASHINGTON, D.C. 20231
www.uspto.gov

APPLICATION NUMBER	FILING/RECEIPT DATE	FIRST NAMED APPLICANT	ATTORNEY DOCKET NUMBER
10/066,755	02/06/2002	Jacob Richter	2390/49902

CONFIRMATION NO. 6124

FORMALITIES LETTER



OC000000007579013

23838
KENYON & KENYON
1500 K STREET, N.W., SUITE 700
WASHINGTON, DC 20005

Date Mailed: 03/05/2002

NOTICE TO FILE CORRECTED APPLICATION PAPERS

Filing Date Granted

This application has been accorded an Application Number and Filing Date. The application, however, is informal since it does not comply with the regulations for the reason(s) indicated below. Applicant is given **TWO MONTHS** from the date of this Notice within which to correct the informalities indicated below. Extensions of time may be obtained by filing a petition accompanied by the extension fee under the provisions of 37 CFR 1.136(a)

The required item(s) identified below must be timely submitted to avoid abandonment:

- Substitute drawings in compliance with 37 CFR 1.84 because:
 - drawing sheets do not have the appropriate margin(s) (see 37 CFR 1.84(g)). Each sheet must include a top margin of at least 2.5 cm (1 inch), a left side margin of at least 2.5 cm. (1 inch), a right side margin of at least 1.5 cm. (5/8 inch), and a bottom margin of at least 1.0 cm. (3/8 inch);

*A copy of this notice **MUST** be returned with the reply.*

Customer Service Center
Initial Patent Examination Division (703) 308-1202

PART 2 - COPY TO BE RETURNED WITH RESPONSE